<b>PCN Number:</b> 20180621000 <b>PCN Date:</b> June 21, 2018		
Title: Datasheet for LMH1218		
Customer Contact:PCN ManagerDept:Quality Set	Quality Services	
Change Type:		
Assembly Site Design Wafer Bump Site		
	er Bump Material	
	r Bump Process	
■ Mechanical Specification       ■ Test Site       ■ Wafer Fab Site         ■ Packing/Shipping/Labeling       ■ Test Process       ■ Wafer Fab Mater		
	Vafer Fab Process	
Notification Details		
Description of Change:		
Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is being updated as summarized below. The following change history provides further details.  Texas Instruments  LMH1218		
SNLS474E _FEBRUARY 2015_REVISED JUNE 2018  Changes from Revision D (December 2017) to Revision E  Page		
Changed the note under Float(Default) setting from: Reserved to: Power down until valid signal detected		
Changed the Acknowledge (ACK) graphic text from: Clock Line Held Low by Receiver While Interrupt is Serviced to:		
Host may held clock line low to delay transaction		
Changed Channel Register 0x80 default from: 0xXX to: 0x20		
Changed the OUT0_VOD bit 7 default from x to 0		
Changed the bit description for the OUT0_VOD bits 7-3 from: drv_0_sel_vod[3:0] default value may change from part to part to: drv_0_sel_vod[3:0] is typically 42 mV per step		
Changed the OUT0_VOD bit 6 default from x to 0		
Changed the OUT0_VOD bit 5 default from x to 1		
Changed the OUT0_VOD bit 4 default from x to 0		
The datasheet number will be changing.		
Device Family Change From: Change To:		
LMH1218 SNLS474D SNLS474E		
These changes may be reviewed at the datasheet links provided. <a href="http://www.ti.com/product/LMH1218">http://www.ti.com/product/LMH1218</a>		
Reason for Change:		
To accurately reflect device characteristics.		
Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / neg	ative):	
No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.		
Changes to product identification resulting from this PCN:		
None.		
Product Affected:		
LMH1218RTWR LMH1218RTWT		

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com