




Premstätten, August 7, 2020

Change Notification CN43-2020


Packing specification change for AS3412-EWLT

Dear Customer,

ams has to update pin orientation of AS3412-EWLT, part number 191150045 on carrier, wherein Pin 1 of the device is located from upper left moving to upper right position in reference to internal specification and figure 3 (1 of 2) of EIA-481 standard.



Reason for change: Standardize the pin 1 orientation from upper left to upper right position near the round sprocket holes.



Timing of change: Effective immediately starting Date Code 1908 and onwards.

Impact on Product : No impact on the product as there will be no change in terms of form, fit, function, and reliability of the devices. Customer is advised to assess their set-up.

Best Regards,

Reinhard Rogy
ams AG
Director Operations Division AOS