



# Product Change Notice

PCN Number: 14-1145-02  
Issue Date: 02-SEPTEMBER-2015

Exar Corporation

[www.exar.com](http://www.exar.com) | Support: [customersupport@exar.com](mailto:customersupport@exar.com)

|                           |                 |                   |                 |                   |
|---------------------------|-----------------|-------------------|-----------------|-------------------|
| <b>PRODUCTS AFFECTED:</b> | XR21V1414IM48-F | XR21V1414IM48TR-F | XR21V1412IL32-F | XR21V1412IL32TR-F |
|                           | XR21V1410IL16-F | XR21V1410IL16TR-F |                 |                   |

## CHANGE CATEGORY:

|  |                                    |   |
|--|------------------------------------|---|
| <input type="checkbox"/> Material          | <input type="checkbox"/> Process   | <input type="checkbox"/> Package          |
| <input checked="" type="checkbox"/> Design | <input type="checkbox"/> Datasheet | <input type="checkbox"/> Packing/Shipping |
| <input type="checkbox"/> Other             |                                    |   |

**DESCRIPTION OF CHANGE:**  
Metal mask change for yield improvement.

**IMPACT OF CHANGE:**  
No impact to product form, fit or function.

**TARGET IMPLEMENTATION DATE:** 02-DECEMBER-2015

Please contact customer support ([customersupport@exar.com](mailto:customersupport@exar.com)) for sample date availability or qualification data

### PROPRIETARY INFORMATION

THIS DOCUMENT CONTAINS INFORMATION WHICH IS THE EXCLUSIVE PROPERTY OF EXAR CORPORATION. DISTRIBUTION, REPRODUCTION OR USE BY OTHERS IS NOT PERMITTED WITHOUT THE EXPRESS WRITTEN AUTHORIZATION OF EXAR CORPORATION.