CHANGE NOTIFICATION



April 17, 2013

Dear Sir/Madam: PCN# 041713

Subject: Notification of Change to LTC3105 Die

Please be advised that Linear Technology Corporation has made a minor change to the LTC3105 die to improve the device performance.

The description of the problem is as follows:

A small percentage of LTC3105 parts may exhibit a loss of output regulation during the wake up portion of Burst Mode operation.

A minor design change to correct this issue has been implemented. Revised silicon samples are now available. No other functional or parametric specifications are affected, and the datasheet is unchanged. The change was qualified by performing characterization over the full operating temperature range. The product built using new die will be shipped with a date code of approximately 1252.

Should you have any further questions, please feel free to contact me at 408-432-1900 ext. 2519, or by email at NGIRN@LINEAR.COM. If I do not hear from you by May 18th, 2013, we will consider this change to be approved by your company.

Sincerely,

Naib Girn Quality Assurance Manager