

Product Advisory


Issue Date: February 17, 2020

Reason:

This is an advisory on original EOL-BCA-01452; Issue date: May 6, 2019.

This is a notification with regard to EOL-BCA-01452, as it relates to RoHS EU directive 2011/65/EU in 2011 and its amendment Directive (EU) 2015/863 of 31 March 2015 that material shipped after March 1st 2020 will continue to have Eutectic bump interconnect metallurgy.

Below is the label information:



How to read the label?

- RoHS Exempt, Non-RoHS Compliant – these are exempt under exemption 15 for shipments per current EU RoHS directive prior to March 1st 2020

Parts Affected:

BCM68181IFSBG
BCM6818GRKFEBG
BCM6818IFSB
BCM68380FKFSBG-U
BCM68380IFSBG-U
BCM68381KFEBG-U
BCM68385CIFSBG-U
BCM68385IFSBG-U