

Product Obsolescence Memo

CHIP DIODES



July, 2017

Select Bourns® Model CDSOT236 and CDNBS08 Series Products to be Discontinued

Due to circumstances beyond Bourns' control, we are unable to continue to offer for sale select Bourns® Models CDSOT236 and CDNBS08 Series products listed below. As a consequence, we are suspending all new orders for these devices effective immediately.

Obsolete Part Numbers	Replacement Part Numbers
CDSOT236-T12LC	CDSOT236-T12C
CDSOT236-T12LC-SP	CDSOT236-T12C
CDSOT236-DSL0312	TISP4G024L1WR-S
CDSOT236-DSL0324	TISP4G024L1WR-S
CDNBS08-SRDA3.3-6	CDNBS08-SRDA3.3-4
CDNBS08-SRDA05-6	CDNBS08-SRDA05-4

Suggested replacement products are available. The replacement devices are close equivalents to the obsolete part numbers functionally, but may not be pin-to-pin compatible. Please contact the Bourns team of Field Application Engineers if you have any questions regarding the suggested replacement parts and your application requirements.

Availability of the discontinued products is limited to the stock on hand in our warehouse and at our distributors' warehouses, and will no longer be available once this stock is depleted. Customers must notify Bourns in writing within 30 days of receipt of this notification if they consider the discontinued product to be "sole sourced" by Bourns. In such cases, Bourns will work with customers to negotiate an appropriate end-of-life purchase for the discontinued products. Products purchased during this time period will be covered by Bourns' standard warranty. Last Time Buy orders for these products will be considered non-cancellable and non-returnable.

Should you have any questions or need additional information, please feel free to contact [Customer Service/Inside Sales](#).