



Stanley Electric Co., Ltd.
Stanley Electric Sales of America, Inc.
36 Executive Park, Suite 230, Irvine, CA 92614
Tel: 949-222-0777
Fax: 949-222-0555

Dear Valued Customers,

Date: Aug 28 2019

Product Discontinuation Notice

First, we would like to express our sincere appreciation for your support in selecting Stanley Optoelectronic Components.

Regarding the status of Through-hole LEDs, market demand continues to decline in favor of new technologies and it is increasingly difficult to maintain material suppliers due to obsolescence.

Consequently, we have decided to discontinue manufacturing Through-hole LEDs by 9/30/2020. Please review your delivery requirements and issue Last Time Buy orders by the end of September, 2019.

We apologize for any inconvenience this may cause and appreciate your immediate attention to this matter.

Product No.: Please refer to the attached P/N lists

Last buy date: Sep 30, 2019

End of Production: Sep 30, 2020

Last delivery date: Mar 31, 2021

Should you have any questions, please contact us at 949-222-0777.

Stanley Electric Sales of America Sales Team

Product Discontinuation Notice (Part Number list)

Last buy date : **Sep 30, 2019**

Last delivery date : **Mar 31, 2021**

Stanley Electric Co., Ltd.

Stanley Electric Sales of America, Inc.

36 Executive Park, Suite 230, Irvine, CA 92614

Tel: 949-222-0777

Fax: 949-222-0555

Date: Aug 14, 2019

Part Number
AAA3137X
AN3803X-4B0
AN3804X-S180K
AN5306X-C70
AN5307B
AN5307B-J703K
ARD7608X-1M-J689R
ARR5314S-1
CDD0002A/VICS1ニツト/D04NJ
DHN510U
DNP342-1
EBR3338S-1-J672K
EFY3362X-2D5-B246
EHR3372X
EHR5334S
EMPG3368SN-HM-J643K
EMPY3362X-J577K
FA3863X
FER3308S-N-792
FER3308S-N-807
FER3308S-N-B115
FHA3C64X-H
FHA3C64X-H-S180K
FHD3C64X-H
FHD3C64X-H-S180K
FHR3C64X-H
FHR3C64X-H-S180K
FHY3C64X-H
FHY3C64X-H-S180K
FKR3863X
FKR3C64X-H
FKR3C64X-H-S180K
FKR5364X
FKY3863X
FKY3C64X-H
FKY5304X-M-J686K

FLA3864X
FLA3864XN-F210K
FLD3864X-J709K
FR3863X
FR3864X
FR3864X-J300K
FY3863X
FY3864X-3C1
GMW3305SC-3BC9
GMW3305SC-B259
GMW3305SC-B260
GMW3809XA3-J706K
GSB3801C-1119
HAN337
HAN337-1
JDN3302C-H-1104-UL
JFN3308S
JGN5306X
KUA0039A
KUA0096B
KUA0103A
KUA0106A
KUA0111A
KUA0112B
KUA0113A
KUA0116A
KUA0123A
MAA3368SN-H-F240K
MPG3338S
MPR3338S
MPR3873X-J300K
MVR3368SN-H-F210K
MVR3368SN-H-J644K
NR510U
PP514-1
PP514-1-H
PS3893X
RYBG3874X-J652K
SFV1101M-10
SFV5A02B-B280
SFV5B01M-B243
SFV5B01M-B281
SFV5B05B-B279
SFV5B05B-B282
TAN5043-1

TDN1101M-22
TDN1103M
TDN324-6
TDN3803X-2B0
THB3801C
THB3801C-F210K
THB3801C-S180K
THB3809X
THB3809X-S180K
THG3801C
THG3801C-F210K
THG3801C-S180K
THG3809X
THG3809X-F210K
THG3809X-S180K
THW3801C
THW3801C-S180K
THW3809X
THW3809X-S180K
TNR3E02H
VRPG3312X
VRPG5614S-J551R
VRPG5641K-620
VRPY3312X
YPY3368S-8C0-B213
YPY3863X
YPY3864X-M-J690K