



CUSTOMER OPERATIONS
 160 RIO ROBLES
 SAN JOSE, CA 95134

PDN #: M000831

DATE: 02-May-2016

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	73M1822-IM/F	N/A	02-Oct-2016	02-May-2018	Part can no longer be manufactured
Discontinuance	73M1822-IMR/F	N/A	02-Oct-2016	02-May-2018	Part can no longer be manufactured
Discontinuance	73M1866B-IM/F	N/A	02-Oct-2016	02-May-2018	Part can no longer be manufactured
Discontinuance	73M1866B-IMR/F	N/A	02-Oct-2016	02-May-2018	Part can no longer be manufactured
Discontinuance	DS28EL35QA-742+2BW	N/A	02-May-2016	02-May-2016	Part can no longer be manufactured
Discontinuance	DS28EL35QA-742+2TW	N/A	02-May-2016	02-May-2016	Part can no longer be manufactured
Discontinuance	MAX14767EVKIT#	N/A	02-May-2016	02-May-2016	EVKIT is No Longer Supported
Discontinuance	MAX14769EVKIT#	N/A	02-May-2016	02-May-2016	EVKIT is No Longer Supported

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 02-Jun-2016