



KYOCERA International, Inc.

46723 Five Mile Rd.

Plymouth, MI 48170

Tel: 248-921-0410

<http://americas.kyocera.com>

## Notice of End of Life #08152019

### KYOCERA Connector Product

Dear Customer,

[August 15<sup>th</sup> 2019](#) - Kyocera International Inc. would like to inform you about end of life for the below connector part numbers located in Table 1. This EOL takes effect immediately.

Table 1, located at the bottom of this document includes a list of known part numbers sold within the North American market along with a suggested replacement if available. We apologize for the inconvenience and thank you for your understanding and cooperation.

Sincerely,

Bill Adam

Distribution Account Manger

KYOCERA International Inc.

[Bill.Adam@kyocera.com](mailto:Bill.Adam@kyocera.com)

Table 1:

Kyocera PN	Description	Suggested Replacement
205061080052856+	Board to Board	205061080051856+
205061080052861+	Board to Board	205061080051861+
205061080052863+	Board to Board	205061080051863+
205061080052871+	Board to Board	205061080051871+
145843050022829+	Board to Board	None
145843054022829+	Board to Board	None
145843060022829+	Board to Board	None
145843064022829+	Board to Board	None
245843050002829+	Board to Board	None
245843054002829+	Board to Board	None
245843060002829+	Board to Board	None
245843064002829+	Board to Board	None