



<b>Title of Change:</b>	Removing suffix '-F155' of marking diagram on datasheet of FGH40T120SMD-F155
<b>Effective date:</b>	24 Jun 2021
<b>Contact information:</b>	Contact your local ON Semiconductor Sales Office or <a href="mailto:Charles.Jiang@onsemi.com">Charles.Jiang@onsemi.com</a>
<b>Type of notification:</b>	This Product Bulletin is for notification purposes only. ON Semiconductor will proceed with implementation of this change upon publication of this Product Bulletin.
<b>Change Category:</b>	Update datasheet to match with physical unit marking diagram
<b>Change Sub-Category(s):</b>	Datasheet/Product Doc change

**Sites Affected:**

ON Semiconductor Sites	External Foundry/Subcon Sites
None	None

**Description and Purpose:**



To remove suffix '-F155' of marking diagram on datasheet, to match with marking diagram of physical unit.

The change will not impact form, fit, or function of product.

TO-247-3LD  
CASE 340CK

TO-247-3LD  
CASE 340CH

**MARKING DIAGRAMS**



- \$Y = ON Semiconductor Logo
- &Z = Assembly Plant Code
- &3 = Numeric Date Code
- &K = Lot Code
- FGH40T120SMD,  
~~FGH40T120SMD-F155~~ = Specific Device Code

**List of Affected Standard Parts:**

**Note:** Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the [PCN Customized Portal](#).

FGH40T120SMD-F155		
-------------------	--	--



---

**Appendix A: Changed Products**

---

**PCN#: PB24128X**  
**Issue Date: Jun 16, 2021**

---

---

Product	Customer Part Number	Qualification Vehicle	New Part Number	Replacement Supplier
FGH40T120SMD-F155		NA		