

PCN Number:	20180124001	PCN Date:	Feb. 1, 2018
Title:	Datasheet for bq2980		
Customer Contact:	PCN Manager	Dept:	Quality Services
Change Type:			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design
<input type="checkbox"/>	Assembly Process	<input checked="" type="checkbox"/>	Data Sheet
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site
<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Material
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Materials
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Process

Notification Details

Description of Change:

Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is being updated as summarized below. The following change history provides further details.



bq2980

SLUSCS3A – OCTOBER 2017 – REVISED JANUARY 2018

Changes from Original (October 2017) to Revision A

Page

• Editorial updates throughout.....	1
• Changed <i>Device Configuration Options</i>	3
• Changed I_{NORMAL} test conditions in <i>Electrical Characteristics</i>	5
• Changed V_{OC} test conditions in <i>Electrical Characteristics</i>	5
• Changed I_{OCD_REC} in <i>Electrical Characteristics</i>	6

The datasheet number will be changing.

Device Family	Change From:	Change To:
bq2980	SLUSCS3	SLUSCS3A

These changes may be reviewed at the datasheet links provided.

<http://www.ti.com/product/BQ2980>

Reason for Change:

To accurately reflect device characteristics.

Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.

Changes to product identification resulting from this PCN:

None.

Product Affected:

BQ298000RUGR	BQ298000RUGT		
--------------	--------------	--	--

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com