

Dear Customer,

With this INFINEON Technologies Information Note we would like to inform you about the following

ILD8150 / ILD8150E Data Sheet Changes

ILD8150 / ILD8150E Data Sheet Changes

► **Products affected:**

Please refer to attached affected product list 1_cip11220

► **Detailed Change Information:**

Subject: Data Sheet changes from version 1.2 to version 1.3

Reason: Electrical parameters added, update of figures

Description:

<u>Old version 1.2</u>	<u>New version 1.3</u>
■ -	■ SD pin reduced pull-up current during shut-down
■ -	■ SD pin initial pull-up current to start shut-down
■ -	■ DIM pin, low power mode current
■ -	■ DIM pin, low power mode voltage
■ Figure 2 Functional block diagram	■ Figure 2 updated
■ Figure 12 Shut down signal interfacing	■ Figure 12 updated

► **Product Identification:**

ILD8150, SP001805682
ILD8150E, SP001805686

► **Impact of Change:**

Improved description of SD/DIM pin

► **Attachments:**

1_cip11220	Affected product list
4_cip11220	Data Sheet version 1.3

► **Intended start of delivery:**

n.a. only Data Sheet change

If you have any questions, please do not hesitate to contact your local Sales office.

InfoNote N° 112/20
ILD8150 / ILD8150E Data Sheet Changes



Sales name	SP number	OPN	Package
ILD8150	SP001805682	ILD8150XUMA1	PG-DSO-8
ILD8150E	SP001805686	ILD8150EXUMA1	PG-DSO-8