

INFORMATION NOTE



N° 099/15

Datasheet update of TLS810C1EJV33 / TLS810D1EJV50 / TLS805B1SJV

Subject of Change: Update of data sheets

Products affected:	Type	SP N°	OPN	Package
	TLS810C1EJV33	SP001179582	TLS810C1EJV33XUMA1	PG-DSO-8 EP
	TLS810D1EJV50	SP001179584	TLS810D1EJV50XUMA1	PG-DSO-8 EP
	TLS805B1SJV	SP001179580	TLS805B1SJVXUMA1	PG-DSO-8

Reason of Change: Data sheet improvement.

DESCRIPTION OF CHANGE:	<u>OLD</u>	<u>NEW</u>
■ Data sheets version	Rev. 1.0	Rev. 1.1
■ Data sheets updates	See Attachment	

Assessment: No change of product (neither of technology/package nor of chip design).

Time Schedule: 2016-02-01

Documentation: 4_cip09915 New Data sheets (Rev. 1.1)
5_cip09915 Data sheets updates

If you have any questions, please do not hesitate to contact your local Sales office.